

Kaagapay ng Komunidad sa Maginhawang Pamumuhay

PURCHASE ORDER

VROOM AUTO CARE CENTER		P.O. No.:	2024-11-208	
	BO. Obrero Barangay 15-B (POB) 8000 Davao City Davao	Date:	11/05/2024	
607-390-654-0000		P.R. No.:	P.R. No.: 2024-09-850	
Mode of Procurement: Negotiated Procurement		Date: 09/25/2024		
h this Office the	e following articles subject to terms and conditions contained h	erein.		
Place of Delivery: SHFC DAVAO OFFICE		Delivery Term: FOB Destination		
Date of Delivery: CHECK ON DELIVERY		Payment Term: Check on Delivery		
Unit	Description	Quantity	Unit Cost	Amount
Lot	Labor Bull John and Lower Ball John BUR # M	1-244-2937	40,480.00	40,480.00
Total Amount in Words: FORTY THOUSAND FOUR HUNDRED EIGHTY AND 00/100 ONLY				40,480.00
In case of failure to make the full delivery within the time specified above, a penalty of one - tenth (1/10) of one percent for every day of delay shall be imposed. Note: This is to approve the BAC recommendation (BAC Reso No. 248, S. 2024) for the use of Alternative Mode of Procurement under sec. 53, 53.9 of IRR of RA9184 and award of contract to above mentioned supplier.				
Conforme: Very truly yours,				
Signature over Printed Name of Supplier Authorized Official 48				
orginature over	Trines traine of Supplier		- Addionized Official	u de a¥s .
Date				
	Chief Accountant			
	Vinzon St. 1 Del Sur 607-390-65 curement: N th this Office the very: SHFC very: CHEC Unit Lot Lot Signature over	Vinzon St. BO. Obrero Barangay 15-B (POB) 8000 Davao City Davao Del Sur 607-390-654-0000 curement: Negotiated Procurement In this Office the following articles subject to terms and conditions contained he wery: SHFC DAVAO OFFICE CHECK ON DELIVERY Unit Description Lot Repair - Motor Vehicle-Repair - Motor Vehicle Replacement of: 2 pes. Rack End Replacement 2 pes. Shock Absorber Rear Replacement 2 pes. Shock Absorber Front Replacement 2 pes. Stabilizer Clamp Bushing 2 pes. Stabilizer Clamp Bushing 2 pes. Stabilizer Link 1 pe Wheel Alignment and Balancing 8 pes. Upper Busching and Lower Ball Joint Labor Replacement of the rack and tie rod, Replacement of the front and bear shock, Replacement of the stabilizer link and clamp bushing, Replacement of the stabilizer link and clamp bushing, Replacement upper and lower bushing and upper and lower ball joint and required the alignment and balancing of wheels. Toyota SHJ900 to tin Words: FORTY THOUSAND FOUR HUNDRED EIGHTY AND 00 wheels. Toyota SHJ900 Toyota SHJ900	Vinzon St. BO. Obrero Barangay 15-B (POB) 8000 Davao City Davao Del Sur 607-390-654-0000 Eurement: Negotiated Procurement h this Office the following articles subject to terms and conditions contained herein. Very: SHEC DAVAO OFFICE CHECK ON DELIVERY Delivery Term Payment Term Lot Repair - Motor Vehicle-Repair - Motor Vehicle Replacement of: 2 pes. Rack End Replacement 2 pes. Shock Absorber Rear Replacement 2 pes. Shock Absorber Front Replacement 2 pes. Stabilizer Clamp Bushing 2 pes. Stabilizer Clamp Bushing 4 pes. Upper Bull Joint and Lower Bull Joint Labor Replacement of the rack and tie rod, Replacement of the front and bear shock, Replacement of the front and bear shock, Replacement of the stabilizer link and clamp bushing, Replacement of the stabilizer link and clamp bushing, Replacement upper and lower bushing and upper and lower bushlighing in different and required the alignment and balancing of wheels. Toyota SHJ900 Toyota SHJ900 Toyota SHJ900 Toyota SHJ900 Date Date Date Date Date Date	Vinzon St. BO. Obrero Barangay 15-B (POB) 8000 Davao City Davao Del Sur 607-390-654-0000 curement: Negotiated Procurement built Office the following articles subject to terms and conditions contained herein. Very: SHFC DAVAO OFFICE CHECK ON DELIVERY Delivery Term: FOB Destination Payment Term: Check on Delivery Lot Replacement of: 2 pes. Rack End Replacement 2 pes. Shock Absorber Rear Replacement 2 pes. Shock Absorber From Replacement 2 pes. Stablizer Clamp Bushing 2 pes. Stablizer Link 1 pe Wheel Alignment and Balancing 8 pes. Upper Bushing and Lower Bushing 1 pes. Upper Bushing and Lower Bushing 2 pes. Subject Link 1 pe Wheel Alignment and bear shock, Replacement of the rack and tie rod, Replacement of the front and bear shock, Replacement of the stablizer link and clamp bushing, Replacement of the stablizer link and clamp bushing, Replacement of the stablizer link and clamp bushing, Replacement and lower bushing and upper and lower ball joint and required the alignment and balancing of wheels. Toyota SH1900 Lin Words: FORTY THOUSAND FOUR HUNDRED EIGHTY AND 00/100 ONLY Lin Words: FORTY THOUSAND FOUR HUNDRED EIGHTY AND 00/100 ONLY Lin Words: FORTY THOUSAND FOUR HUNDRED EIGHTY AND 00/100 ONLY Lin Words: FORTY THOUSAND FOUR HUNDRED EIGHTY AND 00/100 ONLY Signature over Printed Name of Supplier Date Date Date