

## Kaagapay ng Komunidad sa Maginhawang Pamumuhay

Tel/Fax No.: (02) 8817-3168

Standard Form Number: SF-GOOD-60 Revised on: January 08, 2018

Standard Form Title: Request For Quotation

Company Name:		 Date:	
Address:		 Quotation No.:	2024080300185
PhiIGEPS Reg. No.			
	ce on the item/s listed belo representative not later that	al Conditions, stat	ing the shortest time of delivery and
		MARY GRACE	D. MANGAO
		DATA ENCODE	ER

## **General Conditions:**

- ${\bf 1. \ All \ entries \ must \ be \ typewritten/accurate/readable.}$
- 2. Delivery period must be within seven (7) calendar days only.
- 3. Warranty shall be for a period of six (6) months for supplies and materials, one (1) year for equipment, from the date of acceptance by the Procuring Entity.
- 4. Price validity must be within thirty (30) calendar days.
- 5. Bidders must submit Certificate of PhilGEPS registration, updated Business Permit? Mayor's Permit, Notarized Omnibus Sworn Statement (for ABC's above 50k), and Income or Business Tax Return for ABC's above 500k.
- 6. Bidders shall submit original brochures showing specifications of product being offered.
- 7. All bid proposals must be VAT inclusive.

(FAILURE TO DO SO WILL MEAN DISQUALIFICATION OF YOUR BID PROPOSAL.)

Item No.	Item and Description	QTY	Approved Budget (In Php)	BID Price
	Repair - Motor Vehicle-Replacement of:	1	95,000.00	
	Front Expansion Valve			
	Rear Expansion Valve			
	Front Blower Motor			
	Drier (Metal Type)			
	O-ring (12pcs)			
	Freon 134 A (Dual)			
	A/C Oil			
	Solvent			
	Front Cooling Coil (Tentative)			
	Rear Colling Coil (Tentative)			
	A/C Compressor Assembly (Tentative)			
	Expansion Valve Bolt (Tentative)			
	Front Shock Absorber (2pcs)			
	Rear Shock Absober (2pcs)			
	Tie Rod End (2pcs)			
	Rack End (2pcs)			
	Ball Joint Lower (2pcs)			
	Stabilizer Link (2pcs)			
	Stabilize Bar Bushing (2pcs)			
	Motor Oil (7L)			
	Oil Filter			
	Air Filter			
	Fuel Filter			
	2smf battery			
	Aircon Works			
	Pulldown evaporator assembly front & rear for general cleaning			
	and leak test.			
	Romove and replace front expansion valve, rear expansion			
	valve, front blower motor, drier & orings.			
	Pump all lines, dehydrates system, add a/c oil			
	Recharge Freon.			
	Change Oil			
	Remove and replace motor oil and oil filter.			
	Tune up			
	Remove and replace air filter & fuel filter.			

RFQ No.: 2024080300185

	front shock absorber, rear shock absorber, ball joint lower, stabilizer link, stabilizer		
Wheel alignment & c Toyota Innova SJP42			
, and the second	8737 BDO PLAZA PASEO DE ROXAS MAKATI CITY	95,000.00	
1 *	FOB Destination 15 working days upon complete delivery		
	Delivery Period:  Warranty:  PriceValidity:  Payee's Name & TIN:		
After having carefully read a	nd accepted your General Conditions, I/We	e quote you on the item at prices noted	l above.
Printed Name / Signature		No. / Cellphone No	
	16.1	z z.mpnone r.o	